

Attachment 2 Photos

Figure 1 Third Reedy Lake outlet structure (to No 7 Channel)



Figure 2: Third Reedy (TLF3) looking south showing extensive stands of deadwood characteristic of this waterbody.



Figure 3: Middle Reedy and Third Reedy connecting channel (CCF2) showing more complete riparian margin and fringing emergent macrophytes characteristic of the site.



Figure 4: Intermittent Swampy Woodland zone 2, with a weedy understorey with a high cover of *Juncus acutus* (Spiny Rush) on the western side of Third Lake.



Figure 5 Third Reedy Lake Middle Reedy link channel looking towards Third Reedy Lake



Figure 6 Regulating structure between Middle and Third Reedy Lake – to be upgraded.



Figure 7 Third Reedy Lake pump station to 1/7 Channel



Figure 8 Third Reedy Lake looking east from near No7 regulator



Figure 9 *Third Reedy Lake from Murray Valley Highway*

